

## RESIDENTIAL BUILDINGS SUMMARY 12 May 2008 Wenchuan, China Earthquake Dr. Elizabeth Hausler 30 June 2008

Table 1. Common Structural Systems for Residential Buildings

| Structural System   | Examples                    |                             | Problems and Observations   | What Should Be Done  |
|---|-----------------------------|-----------------------------|---|--|
| TIMBER frame with/without<br>masonry skirt and lightweight<br>wall infill of plastered bamboo<br>mat, pitched timber truss roof<br>with clay tiles<br><i>More common for temples,</i><br><i>and community buildings than</i><br><i>houses</i>   | Jiezi City, Near Dujiangyan |                             | ACCEPTABLE. Very few<br>problems observed; collapses<br>of temple and resort-type<br>structures near Gao Yuan<br>were result of ground<br>displacement, not structural<br>issue.  | <b>EXPLORE</b> cultural<br>appropriateness and cost, and<br><b>PROMOTE</b> this type of<br>construction, but probably less<br>common now due cost and<br>availability of timber, cultural<br>preference for masonry system.  |
| UNREINFORCED MASONRY<br>posts mixed with TIMBER<br>frame elements, masonry skirt,<br>and lightweight wall infill of<br>plastered bamboo mat, pitched<br>timber truss roof with clay tiles<br><i>Older construction common for</i><br><i>RURAL workshops, shops and</i><br><i>a few houses</i> | Wear Xiao Yu Dong Bridge    | Wear Xiao Yu Dong Bridge    | ACCEPTABLE. Some<br>collapse of URM posts; issues<br>with timber decay; masonry<br>skirt is not connected to the<br>frame elements.   | EXPLORE cultural<br>appropriateness and cost, and<br>PROMOTE with some<br>modifications to protect the<br>timber against weathering and<br>pests, anchor the masonry skirt<br>to the frame or posts. Like<br>timber frame, probably less<br>common now due cost and<br>availability of timber, cultural<br>preference for masonry system.                    |
| UNREINFORCED MASONRY<br>single story with pitched or<br>hipped, timber log roof<br>covered with clay tiles<br><i>Common for RURAL, single-</i><br><i>story houses and other</i><br><i>buildings</i>   | Near Xiao Yu Dong Bridge    | Gao Yuan Village (Wenchuan) | Performance was MIXED.<br>Performed better than URM<br>with precast concrete plank<br>roof (see next), but buildings of<br>this type collapsed. In some<br>villages, the URM with timber<br>roof remained completely<br>intact or a few cracks, while all<br>URM with precast concrete<br>roofs collapsed. Lighter roof,<br>better workmanship, use of<br>lime in mortar? | For very simple, symmetric,<br>single-story building built with<br>good workmanship, may be a<br><b>VIABLE</b> low-cost option for rural<br>single family houses. Hipped<br>roofs should be promoted to<br>avoid masonry gables.<br>Technical assistance and some<br>seismic analysis/research<br>needed. Or, shift to confined<br>masonry (more expensive). |



## RESIDENTIAL BUILDINGS SUMMARY 12 May 2008 Wenchuan, China Earthquake Dr. Elizabeth Hausler 30 June 2008

| Structural System   | Examples                         |   | Problems and Observations   | What Should Be Done   |
|---|----------------------------------|---|---|---|
| UNREINFORCED MASONRY<br>single or two-story with precast<br>concrete plank roof and floor<br>Very common for RURAL and<br>peri-urban, single or two-story<br>houses and other buildings   | Near Xiao Yu Dong Bridge         | Wear Xiao Yu Dong Bridge  | MOST DEADLY type of rural<br>residential construction.<br>Nearly every pile of rubble that<br>hadn't been cleared at the time<br>of the site visit included<br>precast planks. No connection<br>between the wall and plank,<br>planks are not confined by a<br>ring beam. | <b>PROHIBIT</b> the use of precast<br>concrete planks by providing<br>simple information on the<br>dangers of this technology, and<br>promoting alternatives such as<br>single story URM with timber roof<br>and/or confined masonry. <i>Note</i><br><i>confined masonry may be too</i><br><i>expensive for rural homeowners.</i> |
| UNREINFORCED MASONRY<br>multi-story building with<br>precast concrete plank roof<br>and floors<br><i>3-7 story buildings common in</i><br><i>urban areas, often with open</i><br><i>RC frame ground floor,</i><br><i>occasionally with reinforced</i><br><i>concrete confining tie columns</i><br><i>in upper floors</i>  | Dujiangyan, near Hehuachi Market | Dujiangyan, near Hehuachi Market  | MOST DEADLY for urban<br>residential, school, and<br>commercial construction.<br>Same as the rural dwellings:<br>no or very weak connections<br>between plank and walls,<br>plank and plank; no ring beam,<br>heavy mass above open frame<br>ground floor.                | <b>PROHIBIT</b> the use of precast<br>concrete planks. Prohibit use of<br>unreinforced masonry for multi-<br>story buildings. Use confined<br>masonry instead up to maximum<br>three stories (see Chinese<br>Seismic Code).   |
| <b>CONFINED MASONRY</b> two<br>story buildings<br><i>Seen in a rural, hillside setting,</i><br><i>although probably increasingly</i><br><i>common for new urban multi-</i><br><i>story buildings designed</i><br><i>according to Chinese Seismic</i><br><i>Code. Note news reports</i><br><i>indicate that masonry</i><br><i>structures greater than 3</i><br><i>stories are no longer permitted</i><br><i>in some provinces.</i> | Gao Yuan Village (Wenchuan)      | Pengzhou, confined masonry exterior<br>wall on industrial building. Defining<br>feature of confined masonry is that<br>the tie column is cast after wall is<br>built, and acts primarily in tension to<br>confine the load-bearing masonry. | FLAWLESS – no cracks or<br>other evidence of damage in a<br>quick survey in one village<br>within 500m of possible<br>surface expression of fault<br>rupture.   | USE THIS TECHNOLOGY for<br>up to three stories according to<br>the Chinese Seismic Code.<br>Simple, prescriptive design and<br>construction guidelines and<br>technology dissemination are<br>needed.   |

© 2008 Build Change



## RESIDENTIAL BUILDINGS SUMMARY 12 May 2008 Wenchuan, China Earthquake Dr. Elizabeth Hausler 30 June 2008

| Structural System  | Examples   |            | Problems and Observations     | What Should Be Done                |
|--|------------|------------|-------------------------------|------------------------------------|
| REINFORCED CONCRETE  |            |            | DAMAGED buildings are         | A big question I leave up to       |
| INFILL multi-story buildings in                              |            |            | spread throughout Dujiangyan. | frame with masonry infill is       |
| urban areas  |            |            |                               | problematic but so common and      |
| 2.7 story buildings sommen in                                | A          |            |                               | prevalent in Asia, it's not        |
| 3-7 Story buildings common in<br>urban areas often with soft |            |            |                               | it until another lower-cost easier |
| ground floor   |            |            |                               | to use, more locally available     |
|  | Dujiangyan |            |                               | system exists                      |
|  | , .,       | Dullanovan |                               |                                    |